
MWDS IN-10 (SIGNAL MODULE) Wiring Diagram



Jumpers

10 optically insulated inputs

Uin=(10 to 240)V AC or DC

Uin=(48 to 240)V AC or DC

For RS485 use
twisted pairs cable
LiYCY (TP) 2 x 2 x 0.25

On the last device
turn "120 ohm" switch ON